

2003 Ford Expedition

Ford has 5 mini relays soldered to the board INSIDE the fuse panel held to it with the pins sticking through and soldered on the printed board. On this one, one of the pins on the middle relay has un-soldered from heat. Usually this relay is melted on one or two pins and could be replaced but taking the fuse panel apart isn't for the faint of heart.



